



HIPPOCAMPUS IV

LOA:	36'5" / 11.1m
Year:	2005
LWL:	33'6" / 10.2m
Beam:	11'10" / 3.60m
Draft:	6'7" / 2m
Displacement:	6,200kg / 13,668lb
Hull Material:	GRP
Engines:	1 x VP MD2030 29 hp
Designer:	Stefan Qviberg
Accommodation:	7 berths in 2 cabins and saloon
Builder:	Arcona Yachts
Location:	Henån, Orust - Sweden
Price:	SEK1,785,000 VAT paid in EU

BERTHON

INTERNATIONAL YACHT BROKERS

Ängsvägen 16, 473 33 Henån

T: +46 304 694 000

E: brokers@berthonscandinavia.se

W: www.berthonscandinavia.com

Disclaimer

These particulars have been prepared from information provided by the vendors and are intended as a general guide to the yacht, their accuracy cannot be guaranteed by us. The purchaser should confirm details of concern to them by survey or engineer's inspection. The purchaser should also ensure that the purchase contract properly reflects their concerns and specifies details on which they may wish to rely.

Broker's Comments:

The Arcona 370 was the second yacht from the new generation of Arcona yachts. It was launched two years after the successful Arcona 400. Performance wise - the Arcona 370 became one of the fastest yachts of her size, with an interior much appreciated by families and couples.

The hull and deck is built with vacuum infusion, laminated bulkheads and cabins and the classic Arcona steel frame to add stability. Approx. 80 units were built between 2003-2013.

Arcona 370 HIPPOCAMPUS IV has been in the same family since new. She has been used for sailing in Scandinavian waters and has been stored inside during winter between 2005-2010 and since 2017 and onwards.

HIPPOCAMPUS IV comes with a mainsail, self-tacking jib and a code 0 from UK sails. There is also a gennaker and a spinnaker available, which are both lightly used and in good condition.

The interior offers two cabins with double berth, galley, heads, saloon with two sofas and a large storage space accessible from the cockpit and/or the heads.

HIPPOCAMPUS IV is in general good condition and has been serviced and updated continuously.

Please contact Berthon Scandinavia for further info and booking of viewings!

Key Facts:

- Dark blue hull with white trim lines.
- Epoxy primer – 2022.
- Mast – 2018 (changed from furling mast).
- Standing and running rigging – 2018.
- Line clutches – 2018.
- Removable inner forestay for storm jib - 2018.
- Mainsail - 2018.
- Code 0 – 2019.
- Self-tacking jib – 2013.
- Sprayhood - 2018.
- Cockpit tent - 2018.
- Electric windlass, stainless steel anchor and chain - 2020.
- Batteries – 2022.
- Solar panel 78 W - 2020.
- Plotter – 2018.
- AIS – 2019.
- Media player – 2018.
- Speakers in cockpit - 2019.
- 4 + 3 berths.
- Topping mattresses – 2018.

Disclaimer

These particulars have been prepared from information provided by the vendors and are intended as a general guide to the yacht, their accuracy cannot be guaranteed by us. The purchaser should confirm details of concern to them by survey or engineer's inspection. The purchaser should also ensure that the purchase contract properly reflects their concerns and specifies details on which they may wish to rely.

Construction:

RCD Status: The yacht conforms with the essential safety requirements of Directive 94/25EC or RCDII (2013/53/EU as appropriate (Recreational Craft Directive) and is categorised A – “Ocean”

Hull, Deck & Superstructure Construction:

- Dark blue hull with white decorative lines.
- Hull and deck in sandwich construction.
- Epoxy primer – 2022.
- Antifouling - 2022.
- Teak on the coach roof, cockpit and swim platform.

Keel & Rudder:

- Bolted lead keel.
- Balanced spade rudder.

Machinery:*Engine & Gearboxes:*

- 1 x VP MD2030 29hp.
- Sail drive.
- Sail drive seal – approx. 2015.

*Maintenance & Performance:*

- Engine hour meter display out of order.

Propulsion & Steering:

- 3-blade folding propeller (Volvo Penta).
- Stainless motor control.
- Steering wheels, stainless steel with double spokes, covered with elk skin - 2020.
- Grab bar, stainless steel at the steering pedestal.

Disclaimer

These particulars have been prepared from information provided by the vendors and are intended as a general guide to the yacht, their accuracy cannot be guaranteed by us. The purchaser should confirm details of concern to them by survey or engineer's inspection. The purchaser should also ensure that the purchase contract properly reflects their concerns and specifies details on which they may wish to rely.

Electrical Systems:*Battery Banks:*

- 12 V Service batteries 2 x 120 Ah – 2021.
- 12 V Starter Battery – 2015.

Battery Chargers:

- Battery charger 220 V / 12 V / 20 A.

Shore Power:

- 220 V shore power with earth fault circuit breaker.

Other Electrical:

- Solar panel 78 W (Sunbeam) - 2020.

Plumbing Systems:*Fresh Water & Water Heating System:*

- Hot water approx. 20 L.

Bilge Pumps:

- Electric bilge pump.
- Manual bilge pump.

Tankage:*Fuel:*

- Total capacity of 130 litres (28.59 gallons).

Fresh water:

- Total capacity of 230 litres (50.59 gallons).

Grey/Blackwater holding tanks:

- Septic tank approx. 50 L (10.99 gallons), evacuation via deck and overboard.

Gas:

- Gas bottle.

Navigation Equipment:

- Compass.
- Wind, Log, Depth Instrument (Raymarine ST60).
- Graphic Display (Raymarine ST60+).
- GPS (Raymarine Raynav 300).
- Autopilot (Raymarine ST 6001 Autopilot).
- Remote control for autopilot (Raymarine ST 100).
- Plotter (Raymarine Axiom 9) – 2018.
- AIS (Raymarine AIS 700) - 2019.
- VHF (Ray 240).

Disclaimer

These particulars have been prepared from information provided by the vendors and are intended as a general guide to the yacht, their accuracy cannot be guaranteed by us. The purchaser should confirm details of concern to them by survey or engineer's inspection. The purchaser should also ensure that the purchase contract properly reflects their concerns and specifies details on which they may wish to rely.

Domestic Equipment:*Galley:*

- Gas stove with 2-burners and oven (ENO).
- Fridge box with 12 V compressor.
- Single lever mixer faucet.
- Seawater faucet.
- Double sinks.
- Gas alarm.

Heads/Showers:

- Wash basin.
- Single lever mixer faucet.
- Cupboard for storage.
- Mirror.
- Toilet (Jabsco).
- Shower on the transom.

Heating & Ventilation:

- Diesel heater (Eberspacher D2) blown out in cabins and toilet.

Entertainment:

- Media Player (Pioneer) - 2018.
- Speakers in the salon (Pioneer).
- Speakers in cockpit (Fusion) - 2019.
- TV antenna - function unknown.

Lighting:


- LED lighting (except 4 lights in the saloon).
- Reading lamps with USB chargers at the berths.
- Deck lighting mounted on the mast.
- 3-color and the anchor lantern.
- Engine light.

Accommodation:*Summary of Accommodation:*

- 4 + 3 berths.
- Interior in mahogany.
- White ceiling.

Disclaimer

These particulars have been prepared from information provided by the vendors and are intended as a general guide to the yacht, their accuracy cannot be guaranteed by us. The purchaser should confirm details of concern to them by survey or engineer's inspection. The purchaser should also ensure that the purchase contract properly reflects their concerns and specifies details on which they may wish to rely.

Internal Layout:*Description of layout from forwards:**Forward Cabin:*

- Forward cabin with double berth, shelves, cupboards and wardrobes.
- Spring mattresses - 2005.
- Topping mattresses - 2018.

**Disclaimer**

These particulars have been prepared from information provided by the vendors and are intended as a general guide to the yacht, their accuracy cannot be guaranteed by us. The purchaser should confirm details of concern to them by survey or engineer's inspection. The purchaser should also ensure that the purchase contract properly reflects their concerns and specifies details on which they may wish to rely.

Saloon:

- 2 x Sofas, convertible into berths.
- Saloon table.
- Various storage space.

**Galley:**

- L-shaped galley with good storage space.

**Navigation Area:**

- Navigation area with chart table and drawers for storage.

**Heads Compartment:**

- Bright head with shower.

Disclaimer

These particulars have been prepared from information provided by the vendors and are intended as a general guide to the yacht, their accuracy cannot be guaranteed by us. The purchaser should confirm details of concern to them by survey or engineer's inspection. The purchaser should also ensure that the purchase contract properly reflects their concerns and specifies details on which they may wish to rely.

- Access to storage space / cockpit locker.



Aft Cabin:

- Spacious aft cabin with double berth, wardrobe and shelves.
- Spring mattresses - 2005.
- Bed mattresses - 2018.



Deck Equipment:

Rig:

- Mast with 2 pairs of swept spreaders (Seldén) – 2018.
- Standing rig – 2018.
- Aft stays of dynema with top batten.
- Running rigging – 2018.
- Line clutches - 2018.
- Furler for genoa (Seldén).

Disclaimer

These particulars have been prepared from information provided by the vendors and are intended as a general guide to the yacht, their accuracy cannot be guaranteed by us. The purchaser should confirm details of concern to them by survey or engineer's inspection. The purchaser should also ensure that the purchase contract properly reflects their concerns and specifies details on which they may wish to rely.

- Removable inner forestay for storm jib - 2018.
- Code 0 fittings on the mast and reinforced deck fittings - 2018.
- Aft stay tensioner.
- Rod kick with gas damper (Seldén).
- Spinnaker boom, carbon fiber.
- Rigging screw cover, canvas.
- Windex.

Winches:

- 4 x Winches (Lewmar 40).
- 2 x Winches (Lewmar 16).

Sails:

- Mainsail (UK) - 2018.
- Self-tacking jib (UK) - 2013, overhauled by sailmaker - 2019.
- Code 0 (UK) - 2019.
- Genoa – 2005, sparingly used.
- Gennaker in stocking - 2005, sparingly used.
- Spinnaker in stocking - 2005, sparingly used.
- Storm jib - 2018.

General:

- Cockpit table.
- Safety/bathing ladder.

Anchoring & Mooring Equipment:

- 4 x Cleats.
- 2 x Spring cleats.
- 4 x Mooring lines.
- 4 x Fenders.
- Boathook.
- In the bow:
 1. Electric windlass (Lewmar HX800) - 2020.
 2. Stainless anchor (Bruce type) 15 kg.
 3. 70 m stainless chain - 2020.
- In the stern:
 1. Bruce 15 kg.
 2. 3 m chain.
 3. 40 m anchor line.

Covers, Canvas & Cushions:

- Sprayhood - 2018.
- Cockpit tent - 2018.
- Grab bar aft sprayhood, stainless, covered with elk skin - 2020.

Fire-fighting equipment:

- 2 x Fire extinguishers.

Disclaimer

These particulars have been prepared from information provided by the vendors and are intended as a general guide to the yacht, their accuracy cannot be guaranteed by us. The purchaser should confirm details of concern to them by survey or engineer's inspection. The purchaser should also ensure that the purchase contract properly reflects their concerns and specifies details on which they may wish to rely.

**Disclaimer**


These particulars have been prepared from information provided by the vendors and are intended as a general guide to the yacht, their accuracy cannot be guaranteed by us. The purchaser should confirm details of concern to them by survey or engineer's inspection. The purchaser should also ensure that the purchase contract properly reflects their concerns and specifies details on which they may wish to rely.

**Disclaimer**


These particulars have been prepared from information provided by the vendors and are intended as a general guide to the yacht, their accuracy cannot be guaranteed by us. The purchaser should confirm details of concern to them by survey or engineer's inspection. The purchaser should also ensure that the purchase contract properly reflects their concerns and specifies details on which they may wish to rely.

**Disclaimer**

These particulars have been prepared from information provided by the vendors and are intended as a general guide to the yacht, their accuracy cannot be guaranteed by us. The purchaser should confirm details of concern to them by survey or engineer's inspection. The purchaser should also ensure that the purchase contract properly reflects their concerns and specifies details on which they may wish to rely.

**Disclaimer**

These particulars have been prepared from information provided by the vendors and are intended as a general guide to the yacht, their accuracy cannot be guaranteed by us. The purchaser should confirm details of concern to them by survey or engineer's inspection. The purchaser should also ensure that the purchase contract properly reflects their concerns and specifies details on which they may wish to rely.

**Disclaimer**

These particulars have been prepared from information provided by the vendors and are intended as a general guide to the yacht, their accuracy cannot be guaranteed by us. The purchaser should confirm details of concern to them by survey or engineer's inspection. The purchaser should also ensure that the purchase contract properly reflects their concerns and specifies details on which they may wish to rely.

**Disclaimer**

These particulars have been prepared from information provided by the vendors and are intended as a general guide to the yacht, their accuracy cannot be guaranteed by us. The purchaser should confirm details of concern to them by survey or engineer's inspection. The purchaser should also ensure that the purchase contract properly reflects their concerns and specifies details on which they may wish to rely.

BERTHON
synonymous with yachting since 1877